

Men's Soft Shell Jacket

	xs	s	М	L	XL	2XL	3XL
BODY LENGTH -CB	25	26	27	28	29	30	31
BODY WIDTH -CHEST 1" DWN 1/2	21	22	23	24	26	28	30
BOTTOM WIDTH -RELAXED 1/2	20 1/2	21 1/2	22 1/2	23 1/2	25 1/2	27 1/2	29 1/2
SLEEVE LENGTH FROM CB	33	34	35	36	36 1/2	37	37 1/2

Key to Commonly Abbreviated Spec. Information (all measurements are in inches)

CB = Center Back

Chest 1" down = means you measure the front of the garment 1" down from the armhole

1/2 = Measure only the front of the garment, then double that measurement to get the total circumference

Relaxed = Do not stretch the garment if it has elastic to measure, simply leave the elastic relaxed and measure

Stretched = Stretch the garment if it has elastic to measure, measure stretched